

Install light bar where it does not block cameras, sensors or license plate.  
For bigger trucks it typically works best to have the vertical spacer going up.  
Adjust as appropriate for your specific model of vehicle and light bar size.




Figure 1: Main Bracket

## MAIN BRACKET POSITIONING:

The main brackets can be positioned facing in or facing out to accommodate a variety of light bar sizes:



Main Brackets facing in



Main Brackets facing out



## MAIN BRACKET ATTACHMENT:



Fasten clamp through **hole B**  
and **slot D** in main bracket  
(Fig.1)




See other side for  
positioning guidelines

## GMC SIERRA 2500HD, 3500HD - POSITIONING



**20" Light Bar:**



**30" Light Bar:**



**40" Light Bar:**




It may be necessary to move the license plate down on 30" and 40" bars.

Due to spacing of the recovery hooks on GMC HD Trucks, 50" Light Bars are not recommended for use with this mount.



Version: 00 - Updated: July 24, 2025

Install light bar where it does not block cameras, sensors or license plate.  
For bigger trucks it typically works best to have the vertical spacer going up.  
Adjust as appropriate for your specific model of vehicle and light bar size.



**Figure 1: Main Bracket**

## MAIN BRACKET POSITIONING:

The main brackets can be positioned facing in or facing out to accommodate a variety of light bar sizes:




Main Brackets facing in



Main Brackets facing out

## MAIN BRACKET ATTACHMENT:



Fasten clamp through **hole B**  
and **slot D** in main bracket  
(Fig.1)





See other side for  
positioning guidelines

## GMC SIERRA 2500HD, 3500HD - POSITIONING



**20" Light Bar:**



**30" Light Bar:**



**40" Light Bar:**



It may be necessary to move the license plate down on 30" and 40" bars.

Due to spacing of the recovery hooks on GMC HD Trucks, 50" Light Bars are not recommended for use with this mount.



Version: 00 - Updated: July 24, 2025